

TOWN OF THOMPSON Inland Wetlands Commission

SPECIAL MEETING - SITE WALK

Saturday, March 12, 2022 @ 9:00 AM

The site walk will be initiated at the Weigh Station Trailer located just inside the entrance to 307 Reardon Road.

Please park safely along road shoulders without blocking the driveway.

Should the site walk be cancelled due to weather or snow cover, then a Cancellation Notice will be posted under the Inland Wetlands Commission's Agendas at <u>https://www.thompsonct.org/</u>

The following sites will be visited:

- 1. IWA22002, Strategic Commercial Realty, Inc. 0 West Thompson Rd (Assessor's map 65, block 101, lot 9), earthmoving associated with the mining of 1 million cubic yards of earth materials. portions of which are in the 100-foot upland review area.
- 2. Lot 1 Donovan Drive Subdivision (see Permit IWA17037) owned by Lavallee Construction LLC (Assessor's map 3, block 80, lot 2D), viewing of wetlands for possible re-subdivision into 2 lots.

Respectfully submitted,

Marla Butts Wetlands Agent

Just a reminder - Site walks are for orientation purposes only. Please save specific questions for the meeting.



Property Information

Property ID	104546
Location	0 REARDON RD
Owner	STRATEGIC COMMERCIAL REALTY INC



MAP FOR REFERENCE ONLY NOT A LEGAL DOCUMENT

Town of Thompson, CT makes no claims and no warranties, expressed or implied, concerning the validity or accuracy of the GIS data presented on this map.

Geometry updated October 19, 2021 Data updated March 20, 2019 Print map scale is approximate. Critical layout or measurement activities should not be done using this resource.



Property Information

Property ID	104333
Location	0 DONOVAN DR
Owner	LAVALLEE CONSTRUCTION LLC



MAP FOR REFERENCE ONLY NOT A LEGAL DOCUMENT

Town of Thompson, CT makes no claims and no warranties, expressed or implied, concerning the validity or accuracy of the GIS data presented on this map.

Geometry updated October 19, 2021 Data updated March 20, 2019 Print map scale is approximate. Critical layout or measurement activities should not be done using this resource.